



注意：本图使用第三角投影！

SPECIFICATIONS	
POWER SUPPLY (V)	22-26V
OVERLOAD CAPACITY (%F.S.)	150
FREE AIR RESONANT FREQ. (HZ.)	5000
CROSSTALK (%F.S.)	4.0
NON-LINEARITY (%F.S.)	1.0
HYSTERESIS (%F.S.)	1.0
OPERATING TEMP. RANGE (°C)	-40 TO +100
MASS (KG)	2.5

	Fx	Fy	Fz	NA	NA	NA
<b>CAPACITY (N/Nm)</b>	20000	20000	50000	NA	NA	NA
<b>OUTPUT (V)</b>	4.6	4.6	4.6	NA	NA	NA
<b>BRIDGE RES. (<math>\Omega</math>)</b>	350	350	350	NA	NA	NA

WIRING CODE - TWISTED PAIR			
FUNCTION	COLOR	FUNCTION	CHN5
PWR (+24V)	RED(BLACK) & BLACK(RED)	FX	WHITE(BROWN)
GROUND	BLUE(BLACK) & BLACK(BLUE)	FY	ORANGE(BRROW)
SHIELD	SHIELD CONNECTS TO SENSOR BOBY	FZ	BLUE(BROWN)
-SIGNAL	BROWN(WHITE) & BROWN(ORANGE) & BROWN(BLUE), ALL CONNECTS 5V		
COLOR CODE EXAMPLE: "RED(BLACK)" = RED CABLE IN RED/BLACK PAIR			

**SUNRISE INSTRUMENTS**  
[www.srisensor.com](http://www.srisensor.com)

三轴力传感器  
D130MM

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN MM	M3615C	REV. 0.1
--	--------	-------------